

STANDOFF BRACKET LOCATIONS

ARE ± 1". DO NOT PREDRILL HOLES IN THE

STRUCTURE. HOLES SHOULD BE MATCH DRILLED TO INSURE PROPER ALIGNMENT

## 3D MODEL AVAILABLE IN STEP FILE FORMAT ON OUR WEBSITE



